


Proposed refacing of 1939 George Washington Memorial Highway.
Front of building to be refaced in a colonial brick with a roof extension
to create harmony with surrounding businesses
Awning to wrap around front and side




Wooden fence across front to comply with revitalization plans of Rte 17 corridor
Existing pole sign removed. Monument sign erected within plantings that match those
in median of Rte 17 * See landscape design.

Proposed refacing of 1939 George Washington Memorial Highway.

Front of building to be resurfaced with beaded Hardy Plank and painted in Colonial Colors

- to create harmony with surrounding businesses

Awnings to wrap around front and side



Wooden fence across front to comply with revitalization plans of Rte 17 corridor

Existing pole sign removed, Monument sign erected within plantings that match those in median of Rt- 17 * see Landscape design